POOR LEGIBILITY

ONE OR MORE PAGES IN THIS DOCUMENT ARE DIFFICULT TO READ DUE TO THE QUALITY OF THE ORIGINAL

PRELIMINARY ASSESSMENT

CONTINENTAL CARBON COMPANY
Route 4, Box 423K Stockdale Highway
Bakersfield, CA. 93307

ASPIS # 15-28-0242

Prepared by: Scott A. Flint

Hazardous Materials Specialist
Department of Health Services
Toxic Substances Control Division
Northern California Section

Date: November 23, 1987

EXECUTIVE SUMMARY

The Continental Carbon Co. site (site) is located approximately 13.5 miles west of Bakersfield, in Kern County, California. Continental Carbon Company operated a carbon black production facility at the site for approximately 19 years. During that time, waste disposal practices included direct discharge of process wash waters to at least three open percolation ponds. Disposal of unspecified types and quantities of laboratory reagents to a sanitary septic tank and leach system was also reported. Currently, soils on the site and the adjacent property are contaminated with particulate carbon black residues.

The California Department of Health Services (DHS) Abandoned Site Project identified the site by phone book on September 24, 1982. A Site Drive-by on February 8, 1983 reported that the plant was being dismantled. Concern was expressed about the presence of and disposal of asbestos, which was used on-site as insulating material for pipes in the processing building. Additional information is required to resolve this concern. Further information is also required to better understand the nature of the industrial wastes that were disposed of on-site to assess the health risks from the direct contact and/or inhalation of particulate carbon black residues on the soil surface.

Recommendation at the Federal level is No Further Action under CERCLA. Analysis of the HRS factors indicate that the site will not score high enough for inclusion on the National Priorities List (NPL). Recommendation at the State level includes a medium priority site inspection (SI). The SI should gather additional information to address the data gaps as outlined above.

SITE LOCATION

The Continental Carbon Co. site (site) is located approximately 13.5 miles west of Bakersfield, in Kern County, California. The site is situated to the south of Stockdale Highway near the intersection of Stockdale and Enos Lane. The last known mailing address was Continental Carbon Co. Route 4, Box 423 K Stockdale Highway Bakersfield, CA 93307. The latitude and longitude coordinates are: 35° 21'03" N and 119° 14'22" W (1,2).

SITE HISTORY

Description of Operations and Processes.

Continental Carbon constructed a carbon black manufacturing plant at the site in 1961. The plant operated until 1979-1980. The initial production capacity was reported at 38 million pounds per year of carbon black product, with a design capacity of 50 million pounds per year (3).

The oil furnace process was utilized at Continental Carbon (3). In the oil furnace process, a highly aromatic feed stock oil is converted to the desired grade of carbon black by partial combustion at 1400 to 1650 °C in a refractory lined steel reactor. From the reactor the pyrolyzed carbon black "smoke" is channeled into a tunnel where it is water-quenched to about 200 Further along precipitators, cyclone scrubbers, or bag filters are used to separate the carbon black product from water vapor and the combustion off-gases. Following pulverization and grit removal the carbon black is normally pelletized for convenient bulk handling. Wet pelleting is the most common process, where the black is mixed with water and agitated in a trough, and then dried in a gas-fired dryer. Dry pelleting and oil pelleting processes are also used in the industry. It is unknown exactly which pelleting process or processes were used at Continental Carbon (4).

Types and Quantities of Wastes Produced.

Industrial wastes at the time of the plant's construction were projected to consist of approximately 180 gallons per minute of wash water, containing less than 2% carbon black. The waste water was discharged to two slurry sumps with any overflow going to a third sump. The suspended carbon black settled in the slurry sumps and was periodically removed. Sources of waste water discharge included wet-cyclone scrubber water, compressor cooling water, floor wash water and occasional backwash from a small zeolite water softener (3,5).

In 1968 one of the wet-cyclone scrubbers was replaced with a bag filter, reportedly cutting the volume of waste water nearly in half. The waste water flow reported during the Central Valley Regional Water Quality Control Board (CVRWQCB) 1968 inspection was 50 to 75 gallons per minute. A second bag filter was added in 1969, reportedly eliminating the waste discharge from the scrubbers (5,6).

Domestic sewage was treated by means of septic tanks and a subsurface leach field. Change house shower wastes by-passed the septic tanks and discharged directly to the leach field. The 1968 CVRWQCB inspection report indicated that laboratory waste waters containing small amounts of common reagents were discharged into one of the domestic systems (5).

OWNERSHIP INFORMATION

The current property owner is the Witco Corporation. Their current address is P.O. Box 8587, Woodcliff Lake, New Jersey 07675. Phone: (201) 573-2800. Property at the site was formerly leased to Continental Carbon Co. by Witco (7).

CORPORATE INFORMATION

Continental Carbon Company filed a Statement and Designation by a Foreign Corporation with the California Secretary of State on August 22, 1960. The specific business proposed by Continental Carbon Company was "to manufacture, purchase, use and sell carbon black and all related products and by-products and to conduct all necessary related business activities." Designated agent of process for Continental Carbon Company was CT Corporation System of Delaware (2).

INSPECTION AND ENFORCEMENT HISTORY

The Central Valley Regional Water Quality Control Board (CVRWQCB) adopted industrial and domestic waste discharge requirements (WDR's) for Continental Carbon on July 20, 1961 (8,9). Requirements governing waste disposal were as follows:

- 1. The waste discharge shall not cause a nuisance by reason of odors or unsightliness.
- 2. The waste discharge shall not cause a pollution of adjacent surface or underlying ground waters.

The domestic WDR's were rescinded in 1977, as the waste discharge was adequately regulated by the Kern County Health Department (10). Continental Carbon was inspected by the CVRWQCB for industrial WDR compliance in 1962, 1963, 1967, 1968, 1969, and 1979. Each inspection report noted compliance with the established WDR's.

The California Department of Health Services (DHS) Abandoned Site Project identified the site by phone book on September 24, 1982. A Site Drive-by on February 8, 1983 reported that the plant was being dismantled. Concern was expressed about the presence of and disposal of asbestos, which was used on-site as insulating material for pipes in the processing building. The site was referred to Kern County Health Department on April 13, 1983 (11).

DHS Preliminary Assessment Team Drive-by on July 16, 1987 noted the presence of extensive deposits of carbon black in several locations within the site fence and on the adjacent property to the east of the site (12).

As of this date, no cleanup or closure activities have been documented by CVRWQCB, Kern County Health, or DHS.

OTHER AGENCY INVOLVEMENT

The California Department of Water Resources (DWR) is currently in the planning stages of developing a 25,000 acre groundwater recharge project to the south of the site. This project will result in elevated water levels in the aquifer beneath the site. Concerns involve water quality issues related to Continental Carbon's past disposal practices and the potential mobilization of any contaminants present in the subsurface zone beneath the site when water levels are increased (13).

PROPERTY DESCRIPTION

Section, Township and Range: Section 6, T30S, R26E, MDB&M Assessors Parcel Number: 161-030-21 Zoning Designation: Heavy Industrial (M-3)

The site is located in a rural/agricultural area in Kern County. The site is bounded by Stockdale Highway to the north, agricultural and oil fields to the east and Southern Pacific Railroad tracks to the south and west (14,15).

The site consists of about 35 acres, a majority of which is open, ground sparsely covered with weedy vegetation. The site is abandoned and the plant has been partially dismantled. Six buildings remain on site, the largest of which housed the furnace and associated processing facilities. Seven storage tanks are located above the processing building. Capacity of these tanks is 750 barrels (bbl's) each. Three large storage tanks are located along the western rail spur and are surrounded by a dike. The capacity of these tanks is 5000 bbl's each. According to the Witco Corporation, there are no chemicals, liquids or gases currently stored in the tanks or buildings on the site. No underground storage tanks are known to exists at the site (7,12).

At the southern end of the property are two large impoundments (approximately 100'x75'x20'). The impoundments are empty, their walls are discolored by dusty-looking black deposits. To the west of the impoundments, the soil surface shows signs of recent heavy equipment activity. Within the diked storage tank area there are also signs of recent disturbance and trenching activity (12).

Two wells exist on the property. They are located near the center of the parcel and were identified by the presence of surface pump housings. The electrical power to these wells reportedly has been disconnected (7,12).

The perimeter of the property is secured by a 6 foot, barbed-wire topped, chain link fence and the gate is locked. The property is posted "NO TRESPASSING" (12).

SURROUNDING LAND USE

The immediately adjacent and surrounding lands are zoned for exclusive agriculture (A) (15). The following commercial crops are grown in the area on a rotational basis: alfalfa, barley, cotton and potatoes. A series of active oil wells are located to the southeast and Tenneco West Carbon Pipe yard is located to the east. North of Stockdale Highway are 8 to 10 domestic dwellings (1,12).

DEMOGRAPHICS

Population Within Three Miles.

The projection of a three-mile radius around the site encompasses a portion of Kern County census tracts 32.01, 37 and 38. The total estimated population for these three tracts in 1987 is 10,571. This figure is a projection based on 1980 census data. The actual population residing within the three mile radius is probably significantly less than this, as the site is not located near a major urban area. The random distribution of population centers in rural Kern County does not allow calculation of a more accurate estimate with available data (16,17).

Presence of Sensitive Populations.

Greely School lies approximately 2.75 miles northeast of the site. No other sensitive populations are known to exist within three miles of the site (1).

GEOLOGY

The entire lower San Joaquin Valley consists of a large composite alluvial fan system known as the Kern River Complex. The four general geologic units underlying the region are alluvium, the Tulare formation, Pre-Tulare sediments and the crystalline basement complex (13).

The alluvium is of Pleistocene to Recent age and consists of both older and younger units. The two alluvial units are almost indistinguishable, consisting of a complex of interbedded and discontinuous sand, gravel, silt and clay layers. Clay layers exist near the ground surface in the western portion of the valley explaining the presence of an extensive perched groundwater aquifer in this area. Evidence of clay lenses near the ground surface in the northwest portion T30S, R26E reveal potential areas of localized perched groundwater near the site (13).

The Tulare formation lies below the alluvium. Its thickness varies between 1000 and 2000 feet and it is somewhat less permeable than the alluvium, due to the presence of various mudstone layers. The Tulare formation is separated into upper, unconfined and lower, confined aquifer units by the Corcoran clay. The Corcoran clay consists of a geographically extensive deposit of red to light brown clay, with interbedding layers of sand and silt. The subsurface strata near the site is a a mixture of discontinuous layers indicating that the Corcoran clay is a semi-confining unit in this area (13).

Pre-Tulare sediments consists of marine sand deposits of Pleistocene to Eocene age. These strata are believed to yield little potable water. These rocks overlie the crystalline basement complex which makes up the Sierra Nevada Mountains (13).

SOILS

Soils near the site include various sandy and sandy loam soils, primarily Kibrelina, Cajon, Excelsior and Wasco types. These soil types are considered moderate to rapidly permeable. The soils on-site are described as highly permeable, with permeabilities ranging from 1.4 to 4.2*10⁻³ cm/sec (2 to 6 in/hr) (13).

DESCRIPTION OF AQUIFER

Groundwater Gradient.

In general, groundwater in the area moves radially toward the northwest, west, and southwest from an elongated groundwater mound centered beneath the Kern River (13).

Mapping of groundwater surface elevations in the unconfined aquifer for spring 1986 indicate that the general direction of groundwater movement near the site is to the northwest. The hydraulic gradient near the site is reported to be about 25 feet per mile toward the northwest. Since 1961 the general direction of groundwater movement has remained unchanged, although pumping depressions have altered flow directions somewhat in localized areas south of the Kern River (13,18).

The following regional aquifer hydraulics are summarized from existing literature and presented in CDM's Toxic Assessment Study:

Specific capacity 20 to 80 gpm/ft (Estimated at approximately 60 to 80 gpm/ft near the site.)

Transmissivity 50,000 to 250,000 gpd/ft (Estimated at approximately 250,000 gpd/ft near the site.)

Depth to Groundwater.

Depth to perched groundwater in the summer of 1985 was approximately 10 feet. Depth to groundwater in the unconfined aquifer in spring was approximately 100 feet (18).

A composite aquifer hydrograph for well Cl located in section 10, T30S, R25E, indicates that the water table depth in this area fluctuated between 40 and 190 feet during the period from 1949 to 1982 (13).

Two water wells were drilled on site in January 1961. DWR well data for these wells indicates that groundwater was first encountered at a depth of 72 feet (19).


Water Quality.

The quality of groundwater in the unconfined aquifer varies widely throughout the lower valley, with a total dissolved solids concentration ranging from 120 ppm to over 10,000 ppm. Groundwater near the site is of excellent quality for domestic use with a dissolved solids concentrations of approximately 146 ppm (18).

Groundwater quality in the confined aquifer varies within the same TDS ranges, but in most areas it is considered to be of good to excellent quality. Groundwater in the confined aquifer near the site is of excellent quality with a TDS concentration ranging from 160 ppm to 180 ppm (18).

DISTANCE TO NEAREST WELL AND POPULATION SERVED

Department of Water Resources well logs were collected for 14 wells within approximately two miles of the site. Nine of the wells are listed for domestic use and five wells are listed for irrigation use. Of the nine domestic use wells, seven are relatively shallow (250 to 400 feet) and are drawing from the upper, unconfined aquifer. Two are relatively deep (495 and 525 feet) composite wells, screened in and drawing from both aquifers. Of the five irrigation use wells, two are unconfined wells and three are composite wells (19).



SURFACE WATER

The nearest downgradient surface water flows in the Pioneer Canal, located approximately 800 feet south of the site. The surface slope to the canal is <1% and the canal is flanked by an artificial levee (1).

CLIMATIC DATA

Precipitation and Seasonal Distribution.

The average annual precipitation as reported by the National Oceanic and Atmospheric Administration (NOAA) for the Bakersfield area is 6.61 inches (record years 1977-1986) (20). The average annual evaporation (class A pan) as reported by DWR for the same period is 63.38 inches (21). The average annual net precipitation is -57.07 inches.

Approximately 52% of the average annual precipitation falls during the months of January, February, and March. The average annual precipitation for this three month period is 3.94 inches.

The average annual evaporation is 6.95 inches, and the net is -3.01 inches. The month of January has the single highest average net precipitation, -0.09 inches (20,21).

The maximum 24 hour rainfall for the area, 3.02 inches was recorded in February 1978 (20).

Temperature.

The average daily maximum summer temperatures (OF) are as follows: June 93.2, July 100.7, August 97.9 and September 92.9. Recorded extremes for the above months are 114, 114, 114, and 113 respectively (20).

The average daily minimum winter temperatures are: November 37.5, December 34.9, January 33.7 and February 37.0. Recorded extremes for the above months are 21, 15 13, and 19 respectively (20).

Wind.

The average annual wind speed is 6.4 mph (5.5 knots). Average monthly wind speed is greatest in the months of May and June, 7.9 and 7.9 mph (6.8 knots), respectively. The prevailing wind direction is northwest from March to October and varies between east, northeast, and northwest from November to February (20).

Record peak gust, 58 mph (50.2 knots) was recorded in February, 1986 (20).

CONTAMINANTS

Contaminants at the site include surficial deposits of carbon black product. In this form, the carbon black is a relatively heavy, inert particulate and is insoluble in water.

Polynuclear aromatic compounds (PNA's) occur in natural products such as coal and crude oil. They are generally associated with incomplete combustion of organic materials and are found in smoke from wood, coal, oil and tobacco as well as in tar. PNA's are relatively difficult to remove from waste waters (22). The PNA's are tightly bound to the carbon black particles and are relatively immobile.

Many PNA's are considered highly toxic and are slowly degraded in the environment. Many possess potential for bioaccumulation, carcinogenicity and mutagenicity and their behavior in the environment at trace concentrations is poorly understood (22).

The following information for some common PNA contaminants is summarized by Sax (23).

Benzo(a)pyrene - Sax toxicity rating is 3. Carcinogenic determination: animal positive. It is an experimental carcinogen and teratogen. A common contaminant of water, food and smoke.

Benzo(e)pyrene - Sax toxicity rating is 3. Carcinogenic determination: Animal suspected. Suspected experimental carcinogen.

Dibenz(a,h)anthracene - Sax toxicity rating is 3. Carcinogenic Determination: Animal positive. An experimental carcinogen.

CONCLUSIONS

Continental Carbon Company operated a carbon black production facility at the site for approximately 19 years. During that time, waste disposal practices included direct discharge of process wash waters to at least three open percolation ponds. Disposal of unspecified types and quantities of laboratory reagents to a sanitary septic tank and leach system was also reported. Currently, soils on the site and the adjacent property are contaminated with particulate carbon black residues.

Concerns over disposal of asbestos pipe insulation raised at the time of the plant's destruction have not been resolved to date. Additional information is required to resolve this concern. In addition, further information is required to better understand the nature of the industrial wastes that were disposed of on-site to assess the health risks from the direct contact and/or inhalation of particulate carbon black residues on the soil surface.

HAZARD RANKING (HRS) FACTORS

<u>Direct Contact/Fire and Explosion</u>.

At the present time, the chance for direct contact with surficial deposits of carbon black is small. The site is fenced and posted to restrict access. The surficial contamination outside the fenced area is not extensive and this property is currently surrounded by oilfield operations. The particulate carbon black is not easily dispersed by winds.

There are reportedly no chemicals, liquids or gases stored on-site. The deposits of carbon black on the soil do not pose a fire or explosion hazard.

Groundwater.

Solid carbon black particles are insoluble and are not likely to migrate through the soils to groundwater. PNA's in the surficial carbon black deposits are chemically bound to the carbon and are relatively immobile.

Surface Water.

The carbon black deposits do not pose a threat to surface water. Due to the low amount of rainfall in the area and the flat topography at the site, excessive runoff is not likely. The closest downgradient surface water is protected by an artificial levee.

Other Factors.

The random distribution of population centers in rural Kern County does not allow an accurate calculation of the population within three miles of the site. There are no major population centers within this radius; however, residences in the area are scattered and many appear new. Additional information will be needed if the site is found to pose a significant threat.

RECOMMENDATIONS

EPA Recommendation.

Recommendation at the Federal level is No Further Action under CERCLA. Analysis of the HRS factors indicate that the site will not score high enough for inclusion on the National Priorities List (NPL).

DHS Recommendation.

Recommendation at the State level includes a medium priority site inspection (SI). The SI should gather additional information to address the following:

- 1. Determine if the original asbestos problem at the site has been addressed or if a problem still exists;
- 2. Determine the exact types of industrial processes that were in operation at the site;
- 3. Determine if any additional types of raw materials, chemicals, and/or solvents were used and disposed of on-site; determine if their presence poses a hazard;


- 4. More accurately assess the health risks from, and the likelihood of, direct contact and/or inhalation of the particulate carbon black residues on the soil surface.
- 5. More accurately determine the potential population at risk residing near the site.

P.A. REFERENCES


- 1. Stevens, CA. Quadrangle, 7.5 minute. U.S. Geological Survey (USGS). 1954, photorevised 1968 and 1973.
- Statement and Designation by a Foreign Corporation,
 Continental Carbon Company. CA. Secretary of State Office.
 August 22, 1960. Amendment filed January 21, 1975.
- 3. Supplemental information to Continental Carbon Company File at CVRWQCB. Undated.
- 4. Shreve, R.N. and J.A. Brink, Jr. Chemical Processes Industries 4th Ed. Mc Graw-Hill Book Company. 1977.
- 5. Memorandum from P.E. Jeperson to Charles T. Carnahan, CVRWQCB. Requirement Checking, Continental Carbon Company. October 25, 1968.
- 6. Memorandum from P.E. Jeperson to Charles T. Carnahan, CVRWQCB. Requirement Checking, Continental Carbon Company. August 19, 1969.
- 7. Letter from Witco Corporation to William Brook Baxter, CA. DWR. August 10. 1987.
- 8. Resolution 61-76 Industrial Waste Discharge Requirements, Continental Carbon Company. Central Valley Regional Water Pollution Control Board (now CVRWQCB). Adopted July 20, 1961.
- 9. Resolution 61-75 Domestic Waste Discharge Requirements, Continental Carbon Company. Central Valley Regional Water Pollution Control Board (now CVRWQCB). Adopted July 20, 1961.
- 10. CVRWQCB Order No. 77-65 Rescinding Various Waste Discharge Requirements. Paragraph a. April 22, 1977.
- 11. Site Tracking Sheet. DHS. January 27, 1987.
- 12. Site Drive-by Record. S. Flint and B. Padilla. DHS, Toxic Substances Control Division. July 16, 1987.
- 13. Kern Water Bank Toxics Assessment Study, Final Report.
 Prepared for CA. DWR. Camp, Dresser & McKee Inc. pp. 4-1
 to 4-12. August 1987.

- 14. Assessor's Parcel Map. Bk. 161, Pg. 3. County of Kern. Undated.
- 15. Zoning Map #121. Kern County Department of Planning and Development Services. January 19, 1970. Last amended February 26, 1979.
- 16. Map of Kern County 1980 Census Tracts. Kern County Planning Department.
- 17. Kern County Population, 1980-2010 by Census Tract and census County Division. June 1,1986 update.
- 18. Water Supply Report 1985. KCWA. May, 1986.
- 19. DWR Water Well Drillers Report. Confidential.
- 20. Local Climatological Data Annual Summary with Comparative Data, Bakersfield, California. NOAA. 1986.
- 21. Summary of Agroclimatic Data, Bakersfield 10 NW Agroclimatic Station. DWR 1977-1986 records.
- 22. Sims, R.C. and M.R. Overcash. Fate of polynuclear aromatic compounds (PNAs) in soil-plant systems. In Residue Reviews, vol. 88. Springer-Verlag New York, Inc. 1983.
- 23. I.N. Sax. Dangerous Properties of Industrial Materials, Sixth Edition. Norstrand Reinhold Co. 1984.

APPENDIX A: MAPS



Continental Carbon Co. Kern County, CA.



USGS 7.5'

APPENDIX B: CONTACT REPORTS

AGENCY CONTACT RECORD

AGENCY	CONTACT	DATE	RESPONSE
DIOP FEESUD 3374 E. Simelas Ave.	Dews Williams (209) 445-5044 ATSS 421-	167rd 1981	OK TO WELL ! COPY WELL LOW DATA
CVRWQCB Feeslo	2006 MOREUD (209) 445-5116	16 Seg 1981	WILL CHECK FOR FILES OK TO VIEW
KEEN COUNTY ALLESSONS OFFICE 1415 TENATUR AND	(80%) 861-2311 BAKERSHEUD	77-01 1891	PARCEL FIARS AND CURRENT TAX ROLL INFO. AUAILABLE
KEEN COUNTY PURNING DEPT. 1356 HOER'S BD.	CHERYL A. CASDORAL PLANNER (805) 861 - 2615 BAKEUSHIELD	1750y 1987	PLANUAL INFO AND MARS AVAILABLE.
Keen County Enu. Heauth Bakeestiked	JOHN HARRS (205) 861-3636	17 Juny	OK TO VIEW MUES BAKEBSFIELD AG, KELKO ROTARY COUTHELITAL CARIBON
		 	

APPENDIX C: SITE DRIVE-BY RECORD AND PHOTOGRAPHS

ABANDONED SITE PROGRAM DRIVE-BY RECORD

	Site Name:	CONTINENTAL CARRON (O.
	Site Location	3: Box 423 K STOCKDAUE HIGHWAY
		BAKERSFIELD CA. 93307 KEEN COUNTY
	Facility File	e Number: 15 - 28 - 0242
	1. Status	a. Active () b. Different Company () Inactive
	2. Setting	a. Urban () b. Residential () c. Near: RR tracks () Suburban() Commercial () Drainage () Rural () Industrial (-) Freeway () Agricultural () Other Other
		d. Paved () e. Restricted access () Unpaved () Unrestricted access () Partially paved ()
**	3. Waste	a. Hazardous () b. Liquid () c. Undetermined () Municipal/() Sludge () None visible () Garbage Inert Solid () Other
	4. Waste Contain- ment	a. Pond () b. Drum/Bbl () d. To: Ground () Sump () Pail/Can () Paving () Pit () Trash can () Drain () Dumpster () Other Box/Pallet () C. Piled () Bag/Sack () Tanks ()
		c. Piled () Bag/Sack () Tanks () Scattered () Vehicle () Others
	5. Misc.	a. Odors Nove c. Vegetation
		b. Topography FLAT d. Site observability Excurs
	immediate	the number of people living and/or working in the vicinity of the site. #8 Ducuncs TO N
	7. Estimate productio	the distance to food processing/packaging or agricultural
****		ls, hospitals, nursing homes, day care centers, or other e" populations within NONE.


Abandoned Site Program Drive-by Record Page 2

9. Pr	oximity t	o sensitive	environment/ecosystem	
-------	-----------	-------------	-----------------------	--

10.Map & Comments

A graphic site description. In addition to above, draw, describe, and comment on the following: buildings, paving, storage (raw material and products), security, vacant areas, and housekeeping. Also identify streets, landmarks, directions, etc.

SITE IS 1.9 AI WEST OF NOOD RD. ON S. SIDE OF HILHWAY. ROAD IS PAULD PART OF PALLEDAD SAUR EAST OF BUILDINGS PROCESSING BUILDING ! PAIL SPUB! GROUND COULDED W CARROW BLACK SITE IS FOULED & LOCKED, POSTED NO TRESPOSSING. POWDS ARE EMPTY, BLACK RESIDUE ON SIDES. SILVED ARLA ARLA OF RECEDIT EARTHFIOLING AND A TRENTH DUG IN BEPIMED STOCKDALE HIGHWAY Office I EUNELD WES Beenes اكتدح Chebor Apt Towars PROCESSIUI. WIRWAS Bure Ou Fiers **TRYLLYH** Recent) CARBON BLACK causi ¥20' NOT TO SCALE Bocker



Phono 1. Jecrying of pine, looking a to 0.






Photo 2. View of Large storage tucks ... W side of property

Continental Carbon Company, Sakerafield, CA. Korn Jounty




na bina Nama nation Daga nation (kg beat Daga



lacte ... inpersative capped (2), looking continues.

The second community of the company of the second of the s




lent (f. ismobila) anataillotion oli (anataile) lotion prospetiga locki (f. lock)




Albro A. Jarrianal Compositor De Com Cide of property.

The Company of the Co







State Of California OFFICE OF THE SECRETARY OF STATE

I, MARCH FONG EU, Secretary of State of the State of California, hereby certify:

That the annexed transcript was prepared by and in this office from the record on file, of which it purports to be a copy, and that it is full, true and correct.

IN WITNESS WHEREOF, I execute this certificate and affix the Great Seal of the State of California this

SEP 23 1987



March Foreg Eu

Secretary of State

401373

FILED
In the Office of the Secretary of State
of the State of California

RUE NY MARIE TO SERVE OF SERVE

STATEMENT AND DESIGNATION BY FOREIGN CORPORATION

	CONTINENTAL CARBON COMPANY	
a corporation organized	and existing under the laws of the State of	Delaware
	thate of place or dide of married artists	, makes the following
statements and designation	nc	
1. The location and a	address of its main office is	- 11 An order
4848 Quiton St	reet, Houston, Texas	
2. The location and a	ddress of its principal office in the State of California	
Fiith and Sp Corporation	ring Streets, Los Angeles 13, Calif System	fornia , c/o C T
3. The specific busine	ss it proposes to transact in the State c. California is:	
r <u>To_me</u> mfecture,	purchase, wee and sell carbon black and d	LL_related_products
and by-products	and to conduct all mecessary related bush	ness activities.
To acquire by p	urchase, lesse or otherwise oil and gas la	mds, to produce there-
from oil, gas o use or sell rea activities,	r other volatile and mineral substances. I or personal property necessary in the co	To purchase, leave, hold, mduct of business
4. (4)	C T CORPORATION SYSTEM	, a corporation
		ARE .
is designated as agent up	on whom process directed to the said	
	CONTINUITAL CARBON CONPANY	
may be served within th	e State of California, in the manner provided by law	v. (b) The name of the city.
town or village wherein	said corporate agent has an office, as set forth a	n the certificate filed by and
corporate agent pursua	nt to Section 6403.5 or 6403.6, California Corpo	trations Code, at which the
said	CONTINENTAL CARBON COMPANY	
		may be served is
Los Ange	les	

CONTINENTAL CARBON COMPANY

I have the control of the control of the process directly of upon the agent designated above, and to some of process of Sciences of Sciences of the agent so designated or the agent so control on the agent so control to no longer in those of the agent so control be found at the address given.

CONTINENTAL CARBON COMPANY

A, Allay President

INSTRUCTIONS:

114 · . 1

- 1. This Statement and Designation must be filed in daplicate.
- 2. This statement must be signed by the president, a vice president, the secretary, an assistant secretary, or the treasurer of the corporation.
- 3. There must be annexed to this statement a certificate by the public officer of the state or country having custody of the original articles or certificate of incorporation or of the act creating the corporation, or by a public officer authorized by the laws of such state or country to make such certificate, to the effect that the corporation making the statement is an existing corporation in good standing in the state or country of its incorporation.
- 4. If the corporation change its name or if there be any change in any of the statements made in this statement, then the corporation must file an Amended Statement and Designation, a form of which may be obtained from the Societary of State.



→ 3 Office of Secretary of State.

J. Course M. Schulz, Toordary of Rate of the Hate of Tolarane

do hereby certify that the Certificate of Incorporation of the WITCO CARPON COMPANY, was received and filed in this office the fifth day of November, A.D. 1936, at 9 o'clock A.M.:

And I do nereby further certify that the said "WITCO CARP N COMPANY ... ited a sertificate of Amendment of Certificate of Incorporation changing its corporate title to "CONTINENTAL CARP H COMPANY, on the lifth day of March, A.D. 1937, at 1 o'clock P.M.

And I do hereby further certify that the aforemaid Corporation is duly incorporated under the laws of the State of Delaware and is in good standing and has a legal corporate existence so far as the records of this office show and is duly authorized to transact business:

And I do homeby further certify that the said "CONTINENTAL CAPPOR COMPANY is the last known tide of record of the aforesaid Corporation.

In Testimony Bherrof. Shaneherountosel my hand

and official seal at Dover this diffeenth day of August in the year of our Lord one thousand nine hundred and sixty.



Jang The London 247

A (51311;

FILED

JAN21 19-5

JAN21 19-5

JAN21 19-5

Dentry

Amended Statement and Designation by Foreign Corporation

Continental Carbon Company , a corporation
ng mized and existing under the laws of the State of Delaware
and which is presently qualified for the
ransaction of intrastate business in the State or California, makes the following statements and/or
lesignation:
1. That the name of the corporation has been changed to that bereinshove set forth and that
he name relinquished at the time of such change was **
2. That the location and address of its main office has been changed and the new location and
address of its main office is
3. That the location and address of its principal office in the State of California has been
changed to at carbon black plant located 15 miles Northwest of Bakersfield
on Stockdale Highway, Route 4, Box 423-K, Bakersfield, California 93307
4. The specific business it proposes to transact in the State of California has been changed and
the specific lassiness it now proposes to transact in the State of California in
The second secon
and the second s

B. Of so this present the object to process then designated berein a constraint person in the state of California above couple . This in a condense of these is is hereby designated as its new agent upon a bour process directed to the corporation on a baserved within the State of California on the manner provided by law. (Note: Tutto the forms of tiese of the receiver. After a continuers in Indicate children herboards or a perform 7. (Use this prengraph of the new process agent designated hereby is a comparation. See instructions.) , a corporation organized and existing under the laws of is designated as new agent, upon whom process directed to the undersigned corporation may be served within the State of Celifornia, in the manner provided by law. The name of the city, town or village wherein said cornerate agent has an office, as set forth in the combrate filed by said corporate agent pursuant to Section 3301.5 or 3301.6 of a domestic corporation) or pursuant to Section 6403.5 or 6403.6 (if a foreign corporation). California Corporations Code, at which the undersigned corporation may be served is CONTINENTAL CARBON COMPANY

PARRECTIONS

- 1. Use only whichever of the foregoing paragraphs of this Amended Statement are applicable.
- 2. If this Amended Statement shows a change of corporate name, there must be attached to this Amended Statement a certificate of the public officer having custody of the original corporation documents in the state or place of incerporation to the effect that such change of name was made in accordance with the less of the state or place of incorporation.
- 3. No domestic or forcing corporation may be designated as agent for the service of process unless it has filled with the Secretary of State the certificate provided for by Sections 3204.5 or 6403.5, respectively. California Corporations Code.
 - 4. For filing and recording this Amended Statement there is a fee of \$7.00.

Supplemental Information Continental Carbon Company Kern County

The Continental Carbon Company is constructing a rlant for the manufacture of carbon black from fuel oil west of Eakersfield in Kern County. Initial capacity is 38,000,000 lbs. per year with a design capacity of 50,000,000 lbs. per year. Plant will operate three shifts and have a total of 45 employees.

Domestic sewage will be treated by means of septic tanks and discharged to sub surface leeching fields for disposal. Change house shower wastes will by-pass the septic tanks and discharge directly to the leeching fields. Industrial waste will consist of approximately 180 gallons per minute of wash water containing less than 2 % carbon black, with a small quantity of boiler slow down and occasional backwash from a small zeolite water softner. These wastes will discharge to either of two small percolation sumps located on the plant property.

No threat of pollution or nuisance is anticipated from materials to be found in the waste waters. However, requirements are designed to prevent the discharges from causing nuisance or pollution by any means.

MEMORANDUM

TO:

Charles T. Carnahan

FROM:

P. E. Jepperson

SUBJECT:

Requirements Checking, Continental Carbon Company

On 17 October 1968 I visited the subject carbon black manufacturing plant to ascertain compliance of the discharge with the Board's requirements. Inspection was made in company with Mr. Ireland, Assistant Manager.

Domestic wastes are treated and disposed of in two septic tank/dry well systems. One of these was replaced during the past year because of failure of the leaching field. Laboratory waste waters containing small amounts of common reagents are discharged into one of the domestic systems.

Industrial waste waters are discharged to two slurry sumps, with any overflow going to a third sump. These wastes consist of compressor cooling water, floor wash water and wet-cyclone scrubber water. The only material present in these waters other than naturally occurring minerals is suspended carbon black, which settles in the slurry sumps and is periodically removed. At the time of my inspection one sump was dry, one contained a few feet of black liquid and the third was being cleaned. A flow of 50 to 75 gpm was entering the second sump. No odors, nuisance conditions or evidence of overflows were present.

Mr. Ireland mentioned that one of the two wet cyclone scrubbers was taken out of service during the past year and replaced with a bag filter, cutting the volume of waste water nearly in half. The remaining cyclone will probably be removed in the near future.

My inspection indicates that these discharges are currently meeting the Board's requirements.

10/25/68

pej/jw

cc: Continental Carbon Co.

MEMORANDUM

TO:

Charles T. Carnahan

FROM:

P. E. Jepperson

SUBJECT: Requirements Checking, Continental Carbon Company

On 17 July 1969 I visited the subject carbon black manufacturing plant to ascertain compliance of the discharge with the Board's requirements. Inspection was made in company with Mr. Ireland, Assistant Manager.

Domestic wastes are treated and disposed of in two septic tank/dry well systems. The soil overlying these systems was found to be dry, indicating that the wastes are contained underground.

Industrial wastes, consisting of compressor cooling water and floor wash waters, are disposed of in three percolation and evaporation sumps. Two of these sumps were observed to be half full of liquid and the third was dry, indicating ample capacity to contain the wastes. Waters discharged to these sumps contain suspended carbon black particles but are otherwise unchanged from the water supply. A third source of waste, from wet cyclone scrubbers, has been eliminated with the installation of a second bag filter.

My inspection indicates this discharge is currently meeting the Board's requirements.

8/19/69

pej/jw

cc: Continental Carbon Co.

Witco~

John - FIL Ref 7

Witco Corporation, P.O. Box 8587, Woodcliff Lake, New Jersey 07675 Telephone 201-573-2800

August 10, 1987

Mr. William Brook Baxter Real Estate Branch Division of Land and Right of Way Department of Water Resources P. O. Box 388 Sacramento, CA 95802

Re: Continental Carbon, Bakersfield, Ca. Temporary Entry Permit

Dear Mr. Baxter:

We are responding to your letter of June 1, 1987 requesting temporary access to our property, formerly leased to Continental Carbon, in Bakersfield, Ca. Over the past two months we have received and responded to inquiries from Camp Dresser McKee, whom we believe to be the Division of Water Resources' consultant for the Kern County Groundwater Banking Project Feasability Study. We believe we have answered all the questions that CDM had. A copy of our response to CDM is enclosed for your information.

Should the Department or Camp Dresser Mckee have any further specific questions or requests, we will try to accommodate you. We do not wish to grant the blanket Temporary Entry Permit you have requested, however.

Please call if I can be of further assistance at 201/573-4719.

Sincerely,

WITCO CORPORATION

Manager.

Environmental Projects

EJM/ab

encl.



Witco Corporation, P.O. Box 8587, Woodcliff Lake, New Jersey 07675 Telephone 201-573-2800

July 13, 1987

Mr. Frank Postillion Project Engineer Camp Dresser & McKee, Inc. 2302 Martin Street Irvine. Ca. 92715

RE: Point and Non Point Source Assessment Kern County Groundwater Banking Project Continental Carbon, Bakersfield, Ca.

Dear Mr. Postillion:

We are responding to your letter of May 12, 1987, regarding the Continental Carbon property located at 27000 Stockdale Highway, Bakersfield, Ca. Witco has acquired Continental Carbon and currently owns the property. Future correspondence if required, will be directed to my attention. We have researched your questions and reached the following conclusions:

- 1. There are ten empty aboveground storage tanks at this facility. Seven of these tanks are located along the eastern rail spur. Capacity of these tanks is 750 barrels each. Three tanks are located along the western rail spur. Capacity of these three tanks is 5000 barrels each. To the best of our knowledge, there are no underground tanks.
- There are no chemicals, liquids or gases stored in tanks or buildings at the facility. During plant operations, petroleum oils were converted to carbon black and blended with molasses.
- 3. Minor spills have occurred within the diked area surrounding the 5000 bbl tanks. These petroleum oil spills have all been contained within the diked area.
- 4 & 5. Brine was never handled on site or generated in the carbon black manufacturing process.
 - 6. Water wells (2) are on site and are useable, although power to the pumps has been disconnected. These two wells were installed in 1961. Well logs are attached for your information. To the best of our knowledge, no other wells exist on the property, and no wells have been abandoned or destroyed. We have no records of water quality or depth other than the well logs.

Mr. Frank Postillion Camp Dresser & McKee, Inc.

We hope this answers your questions concerning the property. Please contact me at (201) 573-4719 if there are any questions.

Sincerely,

WITCO CORPORATION

Edward J. Malley

Manager, Corporate Engineering

EJM: jme

cc: A. Abram - NYO
P. Colella - WL
L. Gilbert - NYO

W. Grabarek - M. P. H. Rosenblatt - WL

B. Williams - WL

C. E. File

ATTACHMENT NO. . 1

ORIGINAL File Brighal, Deplicate and Iriplicate with the REGIONAL' WATER POLLUTION

WATER WELL DRILLERS REPORT

Herrison 2014, 2017, 2014, Water &

Do Not Fill In No 66567

STATE OF CALIFORNIA

	inental Carbon Com
) OWNER:	
inc The Ralph E. Parsons Co	ompany
Jdms 617 West 7th Street	
Los Angeles 17, Califor	rnia
Wall to	
2) LOCATION OF WELL: Well !	no.2 n Black Plant
	act 1-SC-1852-1-R1
14 mile East of Superior Roa	
2 mile South of Stockdale Hi	
	£1000V
(1) TYPE OF WORK (check):	•
New well T Deepening Recondit	inning [] Abandon []
f absolument, describe material and procedure in It	
(4) PROPOSED USE (cbcck):	(5) EQUIPMENT:
Domestic 🔲 Industrial 🔀 Municipal 🗀	
erigation [Test Well [Other [Cable Dug Well
	
(6) CASING INSTALLED:	If gravel packed
SINGLE TO DOUBLE TO SHE	Durantis from so of Son fit.
0 402 10s 10ga	20 [®] 0 " 72 "
0 402 10-1054	15 3/4"72 1·02"
	., -
ter and size of their extensis. Point	Sin'el provid 1/811403/811
derents and Fielded	
(7) PERFORATIONS:	•
The of performe and Clean cut	
iiZe of performines 1 ¹¹ is., le	ngth, by 1/8th in
	per row Raws per ft.
<u> 82 - 1·02 3=0</u>	enters
•	
(8) CONSTRUCTION:	
For a surface vonitury and provided? 🏖 Yee 🗍 No. To v	
Fase san etests malest squiare pullurane? 🎖 Yan 🔘 No. 15	
	16inch 12 ga.
Conductor pipe. Method of Seaning — Cemented in.	•
(9) WATER LEVELS: Farm Imples	ent & Engine Co.
hysh at which want was first found	
-anding level before perferening	f.
	ft.
ding level after performing 72	
ding level after performing 72 (10) WELL TESTS: For a pump over mode? To 2 No. 16 tee, by when?	

LIFOR	NIA	•		Store Well Other Well	Na	7- /	
ny				Other Well	No.	-/	٠ د تـ
(11) W	ELL	LOG:	<i>y</i> - '	•			
Total depth	10		-n Presi	i of complesses	II	402	
		by release of		factorial, and	l streeters.		
00	10 10	6	"Sand	6011			
6		_12_		w clay			
_75		_ ₅₇ _	_Sand_				
_57	<u> </u>	<u>-30</u> -		M cjsl			
_30		<u>_15_</u>	_Sand				
_15		_53_		ar cjar			
_ <u>53</u>	- -	<u>63_</u>	Sand.				
68		80_	_Yello	y_clay			
_80	<u> </u>	95		ನಾ ಇಕ್ಕಾರ			
_95 _03		750 703	_Icli(on_clay			
755		130		in sand			
130		77.8		ec_esud			
1118	-	160	Yell	on clay			•
160		168	"Coar	e sand	<i>'</i>	/	
168	-	180	Yell	om clay	73/	·	
180	-	200	Coar	se sand	₩		
200	-	21.2	Yell	ज् ट ोश्य	-/-	3:4	<u> </u>
375	-	225		se sand		10,0	7
225		238 252	-Yell	on clay		16	7.
238	•	252	-Coar			7.	· (*)
252 262		262	Yell				20 1977
262		275 283	Coar			· · · · · · · · · · · · · · · · · · ·	134
275		283	-Yelle				
283		295	-Coar				
295		310	-Tell				
310	<u>.</u>	318	-Cear			 -	
318	÷	332	<u>"Yell</u>				
332	<u> </u>	31:5	Coar	<u> දෙනර</u>			
31:5 355	 -	355	Terr	on clay			
		368	Coar	se sand			
368 375		<u> </u>	_	om clay			
381		390		se sand			
390	-	300	_	se sand			•
399	-	102		of clay			
	-		-		·		
	-		**				
	-C	<u> </u>					
			2076			i	
L	-			HA GOS		}	
			-			;	
	•		<u>.</u>				
Val norted	12	-23-	<u> </u>) . Comel	end]-	12,	19 (
WELL DR						•	
			der my jar	isdiction and	this repor	t is true	to the be
my koonied 	_		m जिल्हे	r Well	De-4774	na	
	:-						

dres 1900 hing Road

Bakersfield, California

RY E SLOCUM, EXECUTRIX OF THE GROUP DAN.W. SLOCUM, DECENSED.

Dud...Jen..11.

To simple be and of well). I To we w

RESOLUTION Industrial Waste Discharge Requirements Continental Carbon Company Kern County

Resolution No. 61-76

Adopted: 7/20/61

WHEREAS, Continental Carbon Company proposes to construct facilities for disposal of industrial waste effluent from heir Carbon Black Manufacturing Plant; and

WHEREAS, the Continental Carbon Company Plant is located about 12 miles west of Bakersfield on Stockdale Highway near Enos Lane in Kern County; and

WHEREAS, it is the intent of the Central Valley Regional Water Pollution Control Board to prevent the disposal from causing a nuisance or a pollution; therefore be it

RESOLVED, that the following requirements shall govern the nature of industrial waste disposal by Continental Carbon Company:

- 1. The waste discharge shall not cause a nuisance by reason of odors or unsightliness.
- 2. The waste discharge shall not cause a pollution of adjacent surface or underlying ground waters.

RESOLVED, further, that the discharger may be required to submit technical reports relative to the waste discharge in accordance with the provisions of Section 13055 of Division 7, California Water Code.

If there is any future change in the condition s of the discharge or use of the disposal area, it may be necessary for the Central Valley Regional Water Pollution Control Board to revise these requirements to conform to the new conditions or use.

These requirements do not authorize the commission of any act resulting in injury to the property of another or protect the discharger from his liabilities under Federal, State, or local laws and regulations.

ATTEST:

/s/ JOSEPH S. GORLINSK)
Executive Officer

CENTRAL (Chairman)

VALLEY
REGION

REGION

RESOLUTION Domestic Waste Discharge Requirements Continental Carbon Company Kern County

Resolution No. 61-75 Adopted:

7/20/61

WHEREAS, Continental Carbon Company proposes to construct facilities for treatment and disposal of change house shower wastes and domestic sewage from their Carbon Black Manufac→turing Plant; and

WHEREAS, the Continental Carbon Company Plant is located about 12 miles west of Bakersfield on Stockdale Highway near Enos Lane in Kern County; and

WHEREAS, disposal of effluent will be by sub surface leeching on company property; and

WHEREAS, it is the intent of the Central Valley Regional Water Pollution Control Board to prevent the disposal from causing a nuisance or a pollution; therefore be it

RESOLVED, that the following requirements shall govern the nature of domestic waste disposal by Continental Carbon Company:

- Neither the treatment facilities nor the waste discharge shall cause a nuisance by reason of odors or unsightliness.
- The waste discharge shall not cause a pollution of adja-2. cent surface or underlying ground waters.

RESOLVED, further, that the discharger may be required to submit technical reports relative to the waste discharge in accordance with the provisions of Section 13055 of Division 7, California Water Code.

If there is any future change in the conditions of the discharge or use of the Disposal Area, it may be necessary for the Central Valley Regional Water Pollution Control Board to revise these requirements to conform to the new conditions or use.

These requirements do not authorize the commission of any the discharger from his liavantion control laws and regulations ution control DR. A. FRANK BREWER act resulting in injury to the property of another or protect the discharger from his liabilities under Federal, State, or

SWA PAR

ATTEST:

/s/ JOSEPH S. GORLINSKI

Executive Officer

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD CENTRAL VALLEY REGION

ORDER NO. 77-65

RESCINDING VARIOUS WASTE DISCHARGE REQUIREMENTS

The California Regional Water Quality Control Board, Central Valley Region, finds that, at various times, the Board adopted the following resolutions which are no longer applicable for the reasons shown:

- a. Resolution No. 61-75, adopted 20 July 1961, established waste discharge requirements for a domestic waste discharge from a septic tank percolation system at the Continental Carbon Company's Bakersfield plant. As the waste discharge is adequately regulated by the Kern County Health Department the Resolution is no longer necessary.
- b. Resolution No. 60-10, adopted 18 February 1960, prescribes require-.
 ments for a discharge of wastes to Lindsay Slough from the California
 Packing Corporation on the Hastings Ranch, Solano County. The packing
 shed is no longer operating and the property is under control of a
 new owner who concurs with rescission.
- c. Resolution No. 67-112, adopted 14 April 1967, prohibits the direct discharge of domestic wastewaters from the Delta Yacht Harbor to the waters of Stockton Harbor, San Joaquin County. The Delta Yacht Harbor was removed from the McLeod Lake Area during the development of the City of Stockton's Civic Center Marina Area.
- d. Resolution No. 67-111, adopted 14 April 1967, prohibits the direct discharge of domestic wastewaters from the Uptown Yacht Harbor to the waters of Stockton Harbor, San Joaquin County. The Uptown Harbor was relocated to new facilities on the south side of the Stockton Channel during the development of the City of Stockton's Civic Center Marina Area. The Bank of Stockton subsequently obtained the assets of Uptown Yacht Harbor, Inc., and now operates the dock facilities as the "Yacht Harbor". Domestic wastewater from the Yacht Harbor office and from a holding tank pumpout facility are discharged to the City sewer system.

IT IS HEREBY ORDERED, that the above waste discharge requirements resolutions be rescinded.

I, JAMES A. ROBERTSON, Executive Officer, do hereby certify the foregoing is a full, true, and correct copy of an order adopted by the California Regional Water Quality Control Board, Central Valley Region, on 22 April 1977.

Original signed by James A. Robertson

ATTACHMENT 1 SITE TRACKING SHEET

Site	Name:	CONTINE	HTAL CAR	BON CC) .	
Site	Location:	Route	4 Box	423 K	STOCKDALE	- HICHWAY
			•		307 KE	
Site	ID Number	: <u>15-2</u>				
Site	Screening		PA _	11-23-8	<u>1</u> si _	
	on Summary					
		/				
					<u></u>	
		······································				
						
		<u> </u>				
	*					
		500:	.000	<u> </u>		
Reco	mmendation		- NFA	00 00	6- 14	201
		2TATE	- MED	PRIORIT	Sime INS	PEUTION
						····
Rati	onale/Supp	orting Docum	entation:		**- <u>-</u>	·
				_		AT A MANUAL WITTER
-		·	•			· · · · · · · · · · · · · · · · · · ·
		00= 0				
Supe	rvisor:	L'Umita	ught-	Prepa	rer: <u>5.</u>	UNI
Hour	s Spent:	<u>es</u>		Date:	12-7-	87
ASP			- Ho-	•		

EXECUTIVE SUMMARY

The Continental Carbon Co. site (site) is located approximately 13.5 miles west of Bakersfield, in Kern County, California. Continental Carbon Company operated a carbon black production facility at the site for approximately 19 years. During that time, waste disposal practices included direct discharge of process wash waters to at least three open percolation ponds. Disposal of unspecified types and quantities of laboratory reagents to a sanitary septic tank and leach system was also reported. Currently, soils on the site and the adjacent property are contaminated with particulate carbon black residues.

The California Department of Health Services (DHS) Abandoned Site Project identified the site by phone book on September 24, 1982. A Site Drive-by on February 8, 1983 reported that the plant was being dismantled. Concern was expressed about the presence of and disposal of asbestos, which was used on-site as insulating material for pipes in the processing building. Additional information is required to resolve this concern. Further information is also required to better understand the nature of the industrial wastes that were disposed of on-site to assess the health risks from the direct contact and/or inhalation of particulate carbon black residues on the soil surface.

Recommendation at the Federal level is No Further Action under CERCLA. Analysis of the HRS factors indicate that the site will not score high enough for inclusion on the National Priorities List (NPL). Recommendation at the State level includes a medium priority site inspection (SI). The SI should gather additional information to address the data gaps as outlined above.

ABANDONED SITE PROGRAM DRIVE-BY RECORD

	Site Name:	CONTINENTAL CARRON CO.
	Site Location	: Box 423 K STOCKDAUE HIGHWAY
		BAKERSFIELD CA. 93307 KEEN COUNTY
	Facility File	Number: <u>15-28-0242</u>
	l. Status	a. Active () b. Different Company () Inactive ()
	2. Setting	a. Urban () b. Residential () c. Near: RR tracks () Suburban() Commercial () Drainage () Rural () Industrial (-) Freeway () Agricultural () Other Other
		d. Paved () e. Restricted access () Unpaved () Unrestricted access () Partially paved ()
	3. Waste	a. Hazardous () b. Liquid () c. Undetermined () Municipal/() Sludge () None visible () Garbage Inert H Solid () Other
	4. Waste Contain- ment	a. Pond () b. Drum/Bbl () d. To: Ground () Sump () Pail/Can () Paving () Pit () Trash can () Drain () Dumpster () Other
		Box/Pallet () c. Piled () Bag/Sack () Tanks () Scattered () Vehicle () Others
	5. Misc.	a. Odors Nove c. Vegetation
	·	b. Topography FLAT d. Site observability ExturN
	immediate	the number of people living and/or working in the vicinity of the site. I 8 Duzuurs TO N
	7. Estimate de production	the distance to food processing/packaging or agricultural
> -4		ls, hospitals, nursing homes, day care centers, or other e" populations within NONE.

Abandoned Site Program Drive-by Record Page 2

10.Map & Comments

A graphic site description. In addition to above, draw, describe, and comment on the following: buildings, paving, storage (raw material and products), security, vacant areas, and housekeeping. Also identify streets, landmarks, directions, etc.

SITE IS 1.9 MI WEST OF NOOD RD. ON 5. SIDE OF HILHWAY. ROAD IS PAUCED & PART OF PALLEDAD SPUR RAST OF BUILDINGS PROPESSING BUILDING ! PAIL SPUB! GROWN COWHEN W CAPEON BLACK SITE IS FONCED & LOCKED, POSTED NO TRESPOSSING. POWDS ARE EMPTY, BLACK PESIDUE ON SIDES. OF RECEDIT EARTHIPOUNTS AND A TRENTH DUG IN BHOMED O STRUKTORE HIGHWAY DIFFLE I EUNELO ME Wars CARBOR APE YARD TANKS WIRMPS BUILDIE Ou FIELD TREWH CARROW BLACK RECOUST 100 x 75 caus ¥20 NOT TO SCALE Berens


Appraisal Level Investigation For California Department Of Water Resources

KERN WATER BANK TOXICS ASSESSMENT STUDY

Final Report

Prepared by Camp Dreeser & McKee Inc.

August 1987



a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of GC/MS Analysis for VOLATILE ORGANICS in Water

Camp, Dresser & McKee/DWR

2302 Martin St.

Suite 275

Irvine, CA 92715

Attn: Joe LeClaire

Job#/PO#:

437.0923

Workorder#: Report#:

W12155 R50113

Phone #:

714-752-5452

Date Sampled:

6/12/87

Date Received:

6/15/87

Date Analyzed:

6/24/87

Lab Number:

Sample I.D.:

H61676 KWB1

Concentration Compound (micrograms/liter)

Detection Limit (micrograms/liter)

VOLATILE PRIORITY POLLUTANTS:

Acrolein	ND	1.0
Acrylonitrile	ND	1.0
Benzene	ИD	0.1
Bromoform	ИD	0.1
Carbon Tetrachloride	ND	0.1
Chlorobenzene	ND	0.1
Dibromochloromethane	ND	0.1
Chloroethane	ND	1.0
2-Chloroethylvinylether	ND	1.0
Chloroform	ИD	0.1
Dichlorobromomethane	ND	0.1
1,1-Dichloroethane	ND	0.1
1,2-Dichloroethane	ND Dedictor level=10	0.1
1,1-Dichloroethene	ND 2 Design 18021	0.1
1,2-Dichloropropane	(0,1	0.1
Ethylbenzene	ND	0.1
Methyl Bromide	ND	1.0
Methyl Chloride	ND	1.0
Methylene Chloride	ND	1.0
1,1,2,2-Tetrachloroethane	ND	0.1
Tetrachloroethene	ND	0.1

ND: Not Detected

NA: Not Analyzed

APPROVED

JUN 8 0 1937

רכ חידי בה

Report of GC/MS Analysis for VOLATILE ORGANICS in Water

Lab Number: Sample I.D.:	H61676 KWB1		
Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)	
VOLATILE PRIORITY POLLUTANT	S (continued):		
Toluene	ND	0.5	
1,1,1-Trichloroethane	ND	0.1	
1,1,2-Trichloroethane	ND	0.1	
Trichloroethene	ND	0.1	
Vinyl Chloride	ИD	1.0	
trans-1,3-Dichloropropene	ND	0.1	
cis-1,3-Dichloropropene	ND	0.1	
trans-1,2-Dichloroethene	ND	0.1	
Trichlorofluoromethane	ND	1.0	
VOLATILE NON-PRIORITY POLLU	TANTS:		
Acetone Methylethylketone	ND	1.0	
Methylethylketone	ND	1.0	
Tetrahydrofuran	ND	1.0	
m,p-Xylenes	ND	0.1	
o-Xylene	ИD	0.1	
Styrene	ND	0.5	
cis-1,2-Dichloroethene	ND	0.1	
NON-VOLATILE PRIORITY POLLU	TANTS:		
1,2-Dichlorobenzene	ND	0.5	
1,3-Dichlorobenzene	ND	0.5	
1,4-Dichlorobenzene	ND	0.5	

ND: Not Detected NA: Not Analyzed

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of GC/MS Analysis for VOLATILE ORGANICS in Water

Camp, Dresser & McKee/DWR

2302 Martin St.

Suite 275

Irvine, CA 92715

Attn: Joe LeClaire

Job#/PO#:

437.0923

Workorder#: Report#:

W12155 R50114

Phone #:

714-752-5452

Date Sampled:

6/12/87

Date Received:

6/15/87

Date Analyzed:

6/24/87

Lab Number:

Sample I.D.:

H61677

KWB2

Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)
VOLATILE PRIORITY POLLUTANTS	3:	
Acrolein	ИD	1.0
Acrylonitrile	ND	1.0
Benzene	ИD	0.1
Bromoform	ИD	0.1
Carbon Tetrachloride	. ND	0.1
Chlorobenzene	ND	0.1
Dibromochloromethane	ND	0.1
Chloroethane	ИD	1.0
2-Chloroethylvinylether	ND	1.0
Chloroform	ИD	0.1
Dichlorobromomethane	ND	0.1
1,1-Dichloroethane	ND	0.1
1,2-Dichloroethane	ND	0.1
1,1-Dichloroethene	ND	0.1
1,2-Dichloropropane	ND	0.1
Ethylbenzene	ND	0.1
Methyl Bromide	ND	1.0
Methyl Chloride	ND	1.0
Methylene Chloride	ND	1.0
1,1,2,2-Tetrachloroethane	ND .	0.1

ND

ND: Not Detected Not Analyzed

Tetrachloroethene

APPROVED

0.1

JUN 3 0 1937

פס הדיטבה

Report of GC/MS Analysis for VOLATILE ORGANICS in Water

Lab Number: Sample I.D.:

H61677 KWB2

Sample 1.D.:				
Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)		
VOLATILE PRIORITY POLLUTANT	S (continued):			
Toluene	ND	0.5		
1,1,1-Trichloroethane	ND	0.1		
1,1,2-Trichloroethane	ND	0.1		
Trichloroethene	ND	0.1		
Vinyl Chloride	ND	1.0		
trans-1,3-Dichloropropene	ND	0.1		
cis-1,3-Dichloropropene	ND	0.1		
trans-1,2-Dichloroethene	ND	0.1		
Trichlorofluoromethane	ND	1.0		
VOLATILE NON-PRIORITY POLLU	ITANTS:			
Acetone	ND	1.0		
Methylethylketone	ND	1.0		
Tetrahydrofuran	ND	1.0		
m,p-Xylenes	ND	0.1		
o-Xylene	ND	0.1		
Styrene	ND	0.5		
cis-1,2-Dichloroethene	ND	0.1		
NON-VOLATILE PRIORITY POLLU	JTANTS:			
1,2-Dichlorobenzene	ND	0.5		
1,3-Dichlorobenzene	ИD	0.5		
1,4-Dichlorobenzene	ND	0.5		

ND: Not Detected NA: Not Analyzed

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of GC/MS Analysis for BASE/NEUTRAL EXTRACTABLE ORGANICS in Water

Camp, Dresser & McKee/DWR 2302 Martin St. Suite 275 Irvine, CA 92715 Attn: Joe LeClaire	Job#/PO#: Workorder#: Report#: Phone #:	437.0923 W12155 R50111 714-752-5452
Date Sampled: 6/12/87 Date Extracted: 6/23/87	Date Received: Date Analyzed:	6/15/87 6/30/87
Lab Number: Sample I.D.:	H6167 KWB1	~
Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)
BASE/NEUTRAL EXTRACTABLE- PRIORITY POLLUTANTS:		
Anthracene Benzo(a) anthracene Benzo(a) pyrene Benzo(b) fluoranthene Benzo(g,h,i) perylene Benzo(k) fluoranthene Chrysene Dibenzo(a,h) anthracene Fluoranthene Indeno(1,2,3-c,d) pyrene Phenanthrene Pyrene	ND N	5.0 5.0 5.0 10 5.0 5.0 10 5.0
ND: Not Detected		

Approved by:_____

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of GC/MS Analysis for BASE/NEUTRAL EXTRACTABLE ORGANICS in Water

Camp, Dress 2302 Martin Suite 275 Irvine, CA Attn: Joe	92715
Date Sampled:	6/12/87

Job#/PO#: 437.0923 Workorder#: W12155 Report#: R50112

Phone #: 714-752-5452

Date Sampled: 6/12/87 Date Received: 6/15/87
Date Extracted: 6/23/87 Date Analyzed: 6/30/87

Lab Number: Sample I.D.:

H61677 KWB2

Concentration Detection Limit
(micrograms/liter) (micrograms/liter)

BASE/NEUTRAL EXTRACTABLEPRIORITY POLLUTANTS:

Anthracene	ND	5.0
Benzo(a) anthracene	ND	5.0
Benzo(a) pyrene	ND	5.0
Benzo(b) fluoranthene	ND	5.0
Benzo(g,h,i)perylene	ND	10
Benzo(k) fluoranthene	ND	5.0
Chrysene	ND	5.0
Dibenzo(a,h)anthracene	ND	10
Fluoranthene	ND	5.0
<pre>Indeno(1,2,3-c,d)pyrene</pre>	ND	10
Phenanthrene	ND	5.0
Pyrene	ND	5.0

ND:	Not	Detected	
NA:	Not	Analyzed	
Appr	oved	by:	

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

> Report of Analysis for TOTAL PETROLEUM HYDROCARBONS (Modified 8015)

Camp, Dresser & McKee/DWR

2302 Martin St.

Suite 275

Irvine, CA 92715

Attn: Joe LeClaire

Job#/PO#:

437.0923

Workorder#: W12155

Report#: R50121

Phone #:

714-752-5452

Date Sampled:

6/12/67

Date Received:

6/15/87

Date Analyzed:

6/24-27/87

Sample

Description

Total Hydrocarbons (milligrams/liter)

H61676 KWBl

Lab#

<0.05

H61677 KWB2 <0.05

NA: Not analyzed

Not detected ND:

Minimum detection limit = 0.05 milligrams/liter

Approved by

APPROYED

JUN 2 9 1987

OC OFFICER

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of Inorganic Analyses

Camp, Dresser & McKee/DWR

2302 Martin St.

Suite 275

Irvine, CA 92715

Attn: Joe LeClaire

Job#/PO#:

437.0923

Workorder#: Report#:

W12155 R50110

Phone #:

714-752-5452

Date Received: 6/15/87

Date Sampled: 6/12/87
Date Completed: 6/30/87

Lab#	Sample I.D.	B mg/l	Br mg/l	Alpha pCi/L	2Sigma pCi/L	Beta pCi/L	2Sigma pCi/L	Radon pci/l
H61676	KWB1	<0.027	0.36	7.6	2.1	3.6	1.7	425
H61677	KWB2	<0.027	<0.1	0.9	0.5	0.3	0.5	480
Lab#	Sample I.D.	U mg/l						

H61676 KWB1 NA

NA H61677 KWB2

NA: Not Analyzed

Approved by _____

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of General Mineral Analysis

Camp, Dresser & McKee/DWR

2302 Martin St.

Suite 275

Irvine, CA 92715

Attn: Joe LeClaire

Job#/PO#:

437.0923

Workorder#: W12155 Report#:

R50115

Phone #:

714-752-5452

Date Sampled: 6/12/87

Date Received: 6/15/87

Date Completed: 6/29/87

Sample Lab Number: H61676 Sample ID: KWB1

CATIONS:	(mg/l)	(meq/1)	ANIONS:	(mg/l)	(meg/l)
					
Sodium Potassium Calcium Magnesium	21.6 0.70 36.1 2.5	0.939 0.0179 1.81 0.208	Bicarbonate Carbonate Chloride Sulfate Nitrate-N Fluoride Hydroxide	112 0.164 21 23 1.8 0.17 0.00	1.83 0.00547 0.592 0.479 0.129 0.00895 0.00

CATION SUM = 2.97meq/l ANION SUM = 3.04meq/l

OTHER WATER	OUALITY	PARAMETERS	DETERMINED	(mg/l):

pH (unitless)	7.4	Copper	<0.007
Conductance (umho/cm)	305	Iron	<0.030
Alkalinity	92	Manganese	<0.012
TDS	180	Surfactants	0.02
Hardness	101	Zinc	0.015
Langelier Index	48	Arsenic	<0.001
pH of CaCO3 saturation (25C)	7.88	Barium	0.045
pH of CaCO3 saturation (60C)	7.36	Cadmium	<0.003
Free CO2 (25C)	8.92	Total Chromium	<0.029
		Silver	<0.005
Mercury	<0.0002	Lead	<0.002
Total Selenium	<0.001		

NA: Not Analyzed ND: Not Detected

Approved by

APPROVED

JUN 3 0 1987

OC OFFICER

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of General Mineral Analysis

Camp, Dresser & McKee/DWR

2302 Martin St.

Suite 275

Irvine, CA 92715

Attn: Joe LeClaire

Job#/PO#: 437.0923

Workorder#: W12155

Report#: R50116 Phone #:

714-752-5452

Date Sampled: 6/12/87

Date Received:

6/15/87

Date Completed: 6/29/87

Sample Lab Number: H61677 Sample ID: KWB2

CATIONS:	(mg/1)	(meq/1)	ANIONS:	(mg/1)	(meg/l)
		-			
Sodium Potassium Calcium Magnesium	45.1 0.10 2.6 0.10	1.96 0.00256 0.13 0.00833	Bicarbonate Carbonate Chloride Sulfate Nitrate-N Fluoride Hydroxide	78.4 0.439 15 20 <0.06 0.22 0.00	1.28 0.0146 0.423 0.417 ND 0.0116 0.00

CATION SUM = 2.1 meg/1 ANION SUM = 2.15meg/l

OTHER WATER QUALITY PARAMETERS DETERMINED (mg/l):

pH (unitless)	8.0	Copper	<0.007
Conductance (umho/cm)	215	Iron	<0.030
Alkalinity	65	Manganese	<0.012
TDS	130	Surfactants	0.03
Hardness	6.92	Zinc	0.011
Langelier Index	-1.22	Arsenic	0.01
pH of CaCO3 saturation (25C)	9.22	Barium	<0.012
pH of CaCO3 saturation (60C)	8.68	Cadmium	<0.003
Free CO2 (25C)	1.57	Total Chromium	0.038
		Silver	<0.005
Mercury	<0.0002	Lead	<0.002
Total Selenium	<0.001		1

NA: Not Analyzed ND: Not Detected

APPROVED

JUN 3 0 1937

רט חידיטבה

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of Liquid/Liquid Extraction Analysis for ETHYLENE DIBROMIDE

Camp, Dresser & McKee/DWR

2302 Martin St.

Suite 275

Irvine, CA 92715

Attn: Joe LeClaire

Job#/PO#:

437.0923

Workorder#: W12155

Report#:

R50117

Phone #:

714-752-5452

Date Sampled:

6/12/87

Date Received:

6/15/87

Date Extracted: 6/18/87

Date Analyzed:

6/26/87

Sample I.D. Lab#

EDB : ug/l

H61676 KWBl <0.02

H61677 KWB2

<0.02

Tentative identification by capillary chromatography with selective detectors. Confirmation available upon request. Minimum detection limit: 0.02 ug/1

NA: Not analyzed

Approved by

APPROVED

JUN 3 0 1937

OC OFFICER

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of Analysis for CARBAMATE PESTICIDES - AB1803

Camp, Dresser & McKee/DWR

2302 Martin St.

Suite 275

Irvine, CA 92715

Attn: Joe LeClaire

Job#/PO#:

437.0923

Workorder#:

W12155

Report#: Phone #:

R50119 714-752-5452

Date Sampled:

6/12/87

Date Received:

6/15/87

Date Extracted:

6/18/87

Date Analyzed:

6/30/87

Lab Number:

Sample I.D.:

H61676 KWB1

Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)
Aldicarb	ND	5.0
Benomyl	ND	100
Carbaryl	ND	1.0
Carbofuran	ND	5.0
CIPC	ND	10
Eptam (EPTC)	ND	10
IPC	ND	10
Methomyl	ND	10
Oxamyl	ND	10
Diuron	ИD	1.0

ND: Not Detected NA: Not Analyzed

wile of tworld

APPROYED

JUL 0 2 1907

CO CALICIA

. a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of Analysis for CARBAMATE PESTICIDES - AB1803

Camp, Dresser & McKee/DWR

2302 Martin St.

Suite 275

Irvine, CA 92715

Attn: Joe LeClaire

Job#/P0#:

437.0923

Workorder#: V

W12155

Report#:

R50120

Phone #:

714-752-5452

Date Sampled:

6/12/87

Date Received:

6/15/87

Date Extracted:

6/18/87

Date Analyzed:

6/30/87

Lab Number:

Sample I.D.:

H61677 KWB2

Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter	
· Aldicarb	ND	5.0	
Benomyl	ND	100	
Carbaryl	ND	1.0	
Carbofuran	ND	5.0	
CIPC	ND	10	
Eptam (EPTC)	ND	10	
IPC	ND	10	
Methomyl	ND	10	
Oxamyl	ND	10	
Diuron	ND	1.0	

ND: Not Detected NA: Not Analyzed


Approved by

J. leone

APPROVED


JUL 0 2 1987

ענט הבניטדע



Note: This map is far assessment purposes only. It is not to be construed as portraying legal ownership or divisions of land for purposes of zoning or subdivision low.

ASSESSORS MAP NO.161-03
COUNTY OF KERN



1984 AT SUM

